

615 East 4th Street | Pierre, SD 57501 P605.773.3356 F605.773.6667

Division of Health Systems Development and Regulation
Health Protection

Licensure and Certification
Public Health Preparedness and Response
Rural Health

October 27, 2017

Carol Regier
Keystone Treatment Center
1010 East 2nd St
Post Office Box 159
Canton, SD 57013

Re: Keystone Treatment Center

Dear Ms. Regier:

On September 14, 2017, the South Dakota Department of Health, Office of Health Care Facilities Licensure & Certification conducted a survey of your inpatient chemical dependency facility for compliance with state rules. This visit found deficiencies whereby corrections were required.

We are accepting your plans of correction for the deficiencies. Please notify this office at (605) 773-3356 if you are unable to correct the deficiencies as outlined in your plan of correction.

If you have any questions relating to the deficiencies, contact Todd McCaskell at the Office of Health Care Facilities Licensure & Certification at (605) 773-3356.

Sincerely,

Chris Qualm, Administrator

Chin Quel

OFFICE OF HEALTH CARE FACILITIES LICENSURE & CERTIFICATION CQ:jrj

cc: Melanie Boetel, Division of Community Behavioral Health with copy of PoC (via email)



615 East 4th Street | Pierre, SD 57501 P605.773.3356 F605.773.6667

Division of Health Systems Development and Regulation

Health Protection
Licensure and Certification
Public Health Preparedness and Response
Rural Health

DATE:

September 27, 2017

TO:

Carol Regier, Administrator

Keystone Treatment Center

1010 East 2nd St. PO Box 159

Canton, SD 57013

FROM:

Chris Qualm, Administrator C. Q./

Office of Health Care Facilities Licensure and Certification

615 E. 4th Street

Pierre, SD 57501-1700

RE:

Compliance Survey conducted September 14, 2017

BY:

Travis Nelsen, Sr. Health Facilities Surveyor

SURVEY TYPE:

Environmental Sanitation, Safety, Fire Prevention, and Accessibility

CODE STANDARDS: Administrative Rules of South Dakota (ARSD)

44:78 Inpatient chemical dependency

67:61 Substance Disorders

National Fire Protection Association Code 101 "Life Safety Code" 2000

edition, Chapters1-10 inclusive and chapter 33

Americans with Disabilities Act Accessibilities Guidelines

(ADAAG)

CC:

Melanie Boetel, Accreditation Program Manager

Department of Social Services Division of Behavioral Health

CLASSIFICATION: Inpatient Chemical Dependency Treatment Facility

BED CAPACITY: 122 total capacity



Keystone Treatment Center 1010 East 2^{ed} St. PO Box 159 Canton, SD 57013

INTRODUCTION

Enclosed please find the list of deficiencies relating to state rules identified as a result of the September 14, 2017, survey of your facility by the above surveyor from this office.

The purpose of this visit was to survey the facility and make an evaluation of the operation and to determine its compliance with the above code standards.

We request that you provide this office with your plan of correction stating the completion date for the corrections, the corrective action you have taken, or the plan of correction that you intend to make. The plan must be submitted to our office by October 7, 2017. Please refer to the enclosed Plan of Correction Guidelines in completing your own plan and retain a copy of the correction plan for your own records.

Based on observation and interview on September 14, 2017 the following deficiencies were noted

1. The ninety minute fire rated cross-corridor door located between room 222 and 223 would not close by itself. The door was dragging on the frame and had to be forced shut.

Plan of Correction:

Data of Correction

10/20/17

Maintenance staff will adjust door & Frame until self closure is attained. Risk Manager or his designee will monitor operation of door during monthly fire drills.

Date of Correction.
2. Need to seal the penetrations or holes in the ceiling and walls in the IT/Storage room in the front administration hall. Wires and conduit have been run through the sheetrock of the ceiling and walls leaving holes where smoke and fire can escape.
Plan of Correction:
Maintenance Staff will close holes with Metal Groumet and insulating foam. Safety Officer will verify closure is intact on quarterly walk through.
Date of Correction: 10/20/17
Administrator: and A - Desla
Date: (0/16/17